



STEEL BIKE RACK UNIT - SPACES FOR 5 BICYCLES.



METAL BENCH




METAL LOUVERED TRASH ENCLOSURE



METAL PICKET FENCING



GRAVEL MAINTENANCE STRIP AT BUILDING



WALKWAY AND AMENITY AREAS PAVER



PERIMETER RETAINING WALL IMAGE



AMENITIES AREA RETAINING WALL CHARACTER IMAGE.



GRILL STATION CHARACTER IMAGE.



BLUE SPRUCE – LOCATED ALONG NORTH AVENUE SCREENING THE SITE ENTRANCE PARKING LOT AND FIRE PIT AREA.



WESTERN ARBORVITAE – SCREENING FOR THE FIRE PIT AREA AND ADJACENT TO THE KNIGHTS OF COLUMBUS PARKING LOT.



KWANZAN CHERRY – GROUPS OF THREE LOCATED ON THE LEFT AND RIGHT SIDE OF THE BUILDING'S NORTH AVENUE ELEVATION.



FLOWERING PEAR – LOCATED TO THE LEFT AND RIGHT OF THE BUILDING'S FRONT ENTRANCE AND SOFTENING THE SOUTHEAST FACING FRONT CORNER.



RED MAPLE – LOCATED ALONG NORTH AVENUE AS
A STREET TREE AND OUTSIDE OF THE PERIMETER RETAINING WALL.



FLOWERING CRAB – LOCATED ALONG THE NORTHEAST EDGE OF THE SITE ENTRANCE PARKING LOT.



GINKGO TREE - LOCATED IN THE REAR PARKING LOT.



TUPELO – LOCATED IN THE REAR PARKING LOT AND BEYOND THE PERIMETER RETAINING WALL ADJACENT TO THE WETLAND.



HORNBEAM – LOCATED AT THE REAR FAÇADE OF THE BUILDING.